

**Alaska State Library  
Historical Collections**

**Bayers, Lloyd H., 1911-1968  
Captain Lloyd H. "Kinky" Bayers Collection, 1898-1967  
MS 10**

**Marine General Information Files**

**asl.historical@alaska.gov  
907 465-2925  
PO Box 110571  
Juneau, Alaska 99811-0571**

EAST COAST FISHERMEN

Afraid of W.Coast boats

VG. See pp 79 BOOK 36.

EMPRESS LINERS

"Empress of China" VG pict. pp. 13 S&S Winter 1955  
"Empress of Australia" " ex "Empress of China" above.  
"Empress of Russia" VG pict. pp. 13 S&S Winter 1955

## ENGINES

Steam, gas, diesel,  
Old and new.

1. Information on the first vessel (British) to have the new 'gas turbine' engine. Book 41; pp 15

EUROPEAN WRECKS

Modern times.

1. VG. pict. of French Trawler "Vert Prairial" doomed  
(Book 39 pp 58)

EVANS ENGINE & EQUIPMENT CO.

M.D. 8/13/1955/pp2 ---Has Lake Union property up for sale and plans to move to new location on the N. side of the Lake Wash. Ship Canal.

Architects are now working on plans for a new concrete building, which will include shops, offices and down-town showroom space. Docks will also be constructed on the waterfront of the 2½ acre site.

EXPLOSIONS AT SEA

Larger vessels

1. "Tancred" (See file card on her.)
2. "Fort Stikine" (READERS DIGEST Apr. 1958 pp. 173)

EXPLOSIONS, BOAT

Other than Juneau

~~Emp. 5/21/1928/7 Troller "Dime" explodes and burns at  
dock in Petersburg. Two men, Jack Olson and Herb. Mjorud  
slightly burned. Boat sinks.~~